

MARTIN® REPLACEMENT BLADES

for Richwood® 1C & 1C-ITC Belt Cleaners

Cleans Better, Lasts Longer, Costs Less

Designed for better cleaning performance and longer wear life, Martin® Replacement Blades provide a more cost effective, direct retrofit upgrade for Richwood® 1C and 1C-ITC Belt Cleaners.

Available for quick delivery and installation and backed by local, factory-trained service technicians, Martin® Replacement Blades will clean better, last longer, and cost less through the life of the blade or your money back.





30-Day No-Risk Trial: If you don't like it, simply return it at no cost!

PRIMARY CARTRIDGE

blade with painted steel side plates and end castings

Part Number	Dim "A"	Dim "B"	Weight kg [lbs]	
BUS14368-24UP	609.6 [24.00]	736.6 [29.00]	17.1 [37.7]	
BUS14368-30UP	762.0 [30.00]	889.0 [35.00]	20.1 [44.3]	
BUS14368-36UP	914.4 [36.00]	1041.4 [41.00]	23.3 [51.4]	
BUS14368-42UP	1066.8 [42.00]	1193.8 [47.00]	26.3 [58.0]	
BUS14368-48UP	1219.2 [48.00]	1346.2 [53.00]	29.4 [64.8]	
BUS14368-54UP	1371.6 [54.00]	1498.6 [59.00]	32.5 [71.6]	
BUS14368-60UP	1524.0 [60.00]	1651.0 [65.00]	35.6 [78.5]	
BUS14368-66UP	1676.4 [66.00]	1803.4 [71.00]	38.7 [85.3]	
BUS14368-72UP	1828.8 [72.00]	1955.8 [77.00]	41.8 [92.2]	






BUS14368-KXXUP XX = blade width



metal-tipped blade with painted steel side plates and end castings

Part Number	Dim "A"		Dim "B"		Weight kg [lbs]	
BUS14368-24TP	609.6	[24.00]	736.6	[29.00]	18.6	[41.0]
BUS14368-30TP	762.0	[30.00]	889.0	[35.00]	22.0	[48.5]
BUS14368-36TP	914.4	[36.00]	1041.4	[41.00]	25.4	[56.0]
BUS14368-42TP	1066.8	[42.00]	1193.8	[47.00]	28.8	[63.5]
BUS14368-48TP	1219.2	[48.00]	1346.2	[53.00]	32.3	[71.2]
BUS14368-54TP	1371.6	[54.00]	1498.6	[59.00]	35.7	[78.7]
BUS14368-60TP	1524.0	[60.00]	1651.0	[65.00]	39.2	[86.4]
BUS14368-66TP	1676.4	[66.00]	1803.4	[71.00]	42.6	[93.9]
BUS14368-72TP	1828.8	[72.00]	1955.8	[77.00]	46.1	[101.6]



SECONDARY BLADE ONLY - including mounting hardware (bolts)*

BUS14368-KXXTP XX = blade width



MARTIN ENGINEERING | visit martin-eng.com call 800.544.2947 or 309.852.2384 | email info@martin-eng.com

Form No. L4191-12/22 | © 2022 Martin Engineering Company

^{*} Martin side plates and end castings required for installation

^{*} Martin side plates and end castings required for installation